



# Invoice

# Vintage Iron & Restoration

15931 N 80th St.  
Scottsdale, AZ 85260

Phone # 480-922-2480

Fax # 480-922-5740

E-mailmarks@vintageironandrestoration.com

**PAID**  
10/12/2015

Bill To

						Date	Invoice #
						8/13/2015	3948
Year	Make / Model	Body	Color	Engine	VIN / Plate	Mileage	
1957	BUICK	COUPE	RED		D1079504 - (TX) DYL-1240	10138	
Item	Description					Rate	Amount
1	Gas					20.00	20.00
1	Fuel cap					11.04	11.04T
1	Rebuilt transmission					2,000.00	2,000.00T
	Shop Supplies - 6% of labor - \$30.00 maximum					30.00	30.00T
	8/18/2015					92.00	184.00
2	Removed transmission for build					92.00	368.00
4	9/21/2015					0.00	0.00
	Installed transmission						
5.5	9/25/2015					0.00	0.00
	Diag and repair cooling fan issue-diag a/c added .5 lb r134-worked on window regulator-test drove					0.00	0.00
2.5	9/29/2015					0.00	0.00
	Cleaned and installed new window regulator						
3.5	9/30/2015					0.00	0.00
	Removed window regulator-disassembled both regulators and assembled 1 working out of all the parts-reinstalled					0.00	0.00
0.5	10/1/2015					0.00	0.00
	Evac & recharge a/c system						
2	10/2/2015					275.31	-275.31
	Checked for leaks-charged a/c with 2.5lbs of freon-vent temp of 45* low side 25 high side 275-wiped down vehicle and vacuumed						
-1	Discount						

It is customary to pay for invoiced amount when the work is completed unless other arrangements have been made. Storage charges will apply to all vehicles left over 2 weeks.  
We are not responsible for old parts unless previously arranged.  
We are not responsible for additional issues caused by work performed. Services rendered may expose other issues or problems not covered by this invoice, nor is any warranty implied covering service or parts other than what is on this invoice.

By signing and paying this invoice you agree to all terms and conditions.

Customer \_\_\_\_\_ Date \_\_\_\_\_

<b>Subtotal</b>	\$2,337.73
<b>Sales Tax</b>	\$162.27
<b>Total</b>	\$2,500.00
<b>Payments/Credits</b>	-\$2,500.00
<b>Balance Due</b>	\$0.00



# Invoice

# Vintage Iron & Restoration

15931 N 80th St.  
Scottsdale, AZ 85260

Phone # 480-922-2480

Fax # 480-922-5740

E-mailmarks@vintageironandrestoration.com

**PAID**  
08/11/2015

Bill To

Date

Invoice #

6/15/2015

3807

Year	Make / Model	Body	Color	Engine	VIN / Plate	Mileage
1957	BUICK	COUPE	RED		D1079504 - (TX) DYI-1240	10138

Item	Description	Rate	Amount
2	Carburetors	357.50	715.00T
1	Manifold gasket set	17.46	17.46T
2	Water outlet gasket	2.48	4.96T
1	Valve cover gasket set	16.21	16.21T
1	Push rod gasket set	0.00	0.00T
1	Distributor cap	8.67	8.67T
8	Spark plugs	2.99	23.92T
1	Thermostat	7.02	7.02T
1	Pinion o-ring	7.57	7.57T
1	Diff cover gasket	7.33	7.33T
1	Fuel Sending Unit	95.04	95.04T
1	Water pump	56.87	56.87T
1	Ignition wire set	58.49	58.49T
1	Bulk metal for front shock fabrication	13.29	13.29T
1	Front shocks	44.23	44.23T
1	Exhaust manifolds	687.70	687.70T
2	Exhaust pipe gaskets	7.93	15.86T
1	Outside labor -rebuild fuel sending unit to work with vehicle guages	115.00	115.00
10	gas	5.00	50.00T
	thermostat housing	12.06	12.06T
1	oil filter	8.44	8.44T
6	20w50 vr1 oil	8.29	49.74T
1	Trans filter kit	24.52	24.52T
1	Stoplight switch	14.89	14.89T
1	Battery group 27	118.95	118.95T
	Shop Supplies - 6% of labor - \$30.00 maximum	30.00	30.00T
	Parts Subtotal -----	0.00	2,203.22
3	Level 3 inspection		0.00

**Subtotal**

**Sales Tax**

**Total**

**Payments/Credits**

**Balance Due**

By signing and paying this invoice you agree to all terms and conditions.

Customer \_\_\_\_\_ Date \_\_\_\_\_



# Invoice

# Vintage Iron & Restoration

15931 N 80th St.  
Scottsdale, AZ 85260

Phone # 480-922-2480

Fax # 480-922-5740

E-mailmarks@vintageironandrestoration.com

**PAID**  
08/11/2015

<b>Bill To</b>						<table border="1"> <tr> <th>Date</th> <th>Invoice #</th> </tr> <tr> <td>6/15/2015</td> <td>3807</td> </tr> </table>		Date	Invoice #	6/15/2015	3807
Date	Invoice #										
6/15/2015	3807										
<b>Year</b>	<b>Make / Model</b>	<b>Body</b>	<b>Color</b>	<b>Engine</b>	<b>VIN / Plate</b>	<b>Mileage</b>					
1957	BUICK	COUPE	RED		D1079504 - (TX) DYL-1240	10138					
<b>Item</b>	<b>Description</b>					<b>Rate</b>	<b>Amount</b>				
2.5	Labor 4/18/2015 -remove carburetors to begin rebuild -remove intake and tensioner -remove valley cover -remove valve covers -remove distributor					92.00	230.00				
1	Clean and paint labor 4/18/2015 -clean and paint valley cover and valve covers					46.00	46.00				
2.5	Labor 4/20/2015 -install intake manifold -install spark plugs -rebuild distributor, install Pertronix					92.00	230.00				
5.5	Labor 4/21/2015 -install carburetors -install distributor, change vacuum lines -install and adjust throttle linkage -remove water pump, fan, fan shroud -change thermostat					92.00	506.00				
1	Labor 4/23/2015 -Drained gas tank, Removed gas tank for clean and repair					92.00	92.00				
4.5	Labor 4/24/2015 -Install water pump & Thermostat -Fabricate fan shroud mounting brackets -Make & Install spark plug wires					92.00	414.00				
1	Labor 4/27/2015 -Disassemble rear end for gasket reseal					92.00	92.00				
1.5	Labor 4/28/2015 -Resealed axles-Installed third member-Reassembled rear brakes Outside labor -Gas tank clean & repair					92.00 110.00	138.00 110.00				
2.5	Labor 5/6/2015 -Removed exhaust manifolds					92.00	230.00				
<div>By signing and paying this invoice you agree to all terms and conditions.</div> <div>Customer _____ Date _____</div>						<b>Subtotal</b>					
						<b>Sales Tax</b>					
						<b>Total</b>					
						<b>Payments/Credits</b>					
						<b>Balance Due</b>					



# Invoice

# Vintage Iron & Restoration

15931 N 80th St.

Scottsdale, AZ 85260

Phone # 480-922-2480

Fax # 480-922-5740

E-mailmarks@vintageironandrestoration.com

**PAID**  
08/11/2015

Bill To

Date

Invoice #

6/15/2015

3807

Year	Make / Model	Body	Color	Engine	VIN / Plate	Mileage
1957	BUICK	COUPE	RED		D1079504 - (TX) DYI-1240	10138

Item	Description	Rate	Amount
5	5/13/2015-Tested and installed fuel sending unit-Installed gas tank-Removed driver and passenger door panels-Drilled and tapped window regulators and door pulls-Drilled and tapped passenger rear window regulator-Reassembled passenger side	92.00	460.00
5.5	5/13/2015-Remove front shocks-remove driver side rear quarter panel-remove window regulator-repaired broken spring and reinstalled-disassemble drivers window regulator for repair or replace	92.00	506.00
1	5/16/2015-Fabricate shocks for proper fitment-Remove outer sleeves-press in pins	92.00	92.00
1.5	5/18/2015-Finished shock install and modification	92.00	138.00
3	5/20/2015 repair and rebuild window regulator	92.00	276.00
2	5/22/2015 removed exhaust heat riser-sandblasted manifolds	46.00	92.00
2.5	5/28/2015 Reassemble window regulator and installed-adjusted window alignment-Clean and paint exhaust manifolds	92.00	230.00
3.5	6/1/2015 Cleaned and installed new exhaust manifolds	92.00	322.00
1	6/2/2015 Removed exhaust front pipe-relocated pass side front pipe-started relocating drivers side	92.00	92.00
3	6/4/2015 Fabricate front exhaust pipes and weld in place	92.00	276.00
5	6/5/2015 Changed fuel line to carbs-installed power steering pump & resevoir-installed spark plug wires-primed fuel system-fixed leaks and started vehicle-filled cooling system and found t-stat housing leaking-	92.00	460.00
1.5	6/8/2015 Installed new t-stat housing-filled and bled cooling system-set timing 12 initial and 30 total-repaired throttle linkage-adjusted carbs	92.00	138.00
1.5	6/18/2015 Replaced trans pan gasket & filter-replaced brake light switch-tightened power steering belt	92.00	138.00

**Subtotal**

**Sales Tax**

**Total**

**Payments/Credits**

**Balance Due**

By signing and paying this invoice you agree to all terms and conditions.

Customer \_\_\_\_\_ Date \_\_\_\_\_



# Invoice

## Vintage Iron & Restoration

15931 N 80th St.

Scottsdale, AZ 85260

Phone # 480-922-2480

Fax # 480-922-5740

E-mailmarks@vintageironandrestoration.com

**PAID**  
08/11/2015

Bill To

Date

Invoice #

6/15/2015

3807

Year	Make / Model	Body	Color	Engine	VIN / Plate	Mileage
1957	BUICK	COUPE	RED		D1079504 - (TX) DYL-1240	10138

Item	Description	Rate	Amount
2	7/1/2015 install window regulator and adjust window-installed door panels and handles	92.00	184.00

It is customary to pay for invoiced amount when the work is completed unless other arrangements have been made. Storage charges will apply to all vehicles left over 2 weeks. We are not responsible for old parts unless previously arranged. We are not responsible for additional issues caused by work performed. Services rendered may expose other issues or problems not covered by this invoice, nor is any warranty implied covering service or parts other than what is on this invoice.

By signing and paying this invoice you agree to all terms and conditions.

Customer \_\_\_\_\_ Date \_\_\_\_\_

**Subtotal** \$7,695.22

**Sales Tax** \$166.02

**Total** \$7,861.24

**Payments/Credits** -\$7,861.24

**Balance Due** \$0.00