

Name: Howard Lein
Address:
Telephone: 602-622-2226
Date: 4/28/2006
Vehicle: 1995 Ferrari 355 Spider V.I.N. ZFFPR48A1SO103084 @ 26,866 Miles

DESCRIPTION	TIME	PARTS
Engine out Major Service.		
Replace Belt Pulley Bearings		
Replace Belt Tensioner		
Replace Timing Belts		
Replace Cam Cover Gaskets		
Replace all Oil Seals		
Replace fuel filter		$3989.52
Replace Oil Filter		
Replace air filters		$323.15
Replace Alt Belt		tax
Replace P/S Belt		
Replace Water pump		$4312.67
Replace water hoses		
Install new Spark plugs NGK Iridium		
Mobil 1 15-50w engine oil		
Mobil 1 75-90W. Gear box oil		
Flush all brake and clutch systems fluids		
Flush and add new coolant		
Check Clutch OK		
Install and repair under body panel		
Replace power mirror switch.		
Install left side injection sleeve.		
Inspect Convertible top	$3740.00	
Charge A/C system		
(see photo CD)		
Labor 44 Hours @ $85.00		
TOTAL $8052.67		