

8167 – Partial List of Service Since 2005 with Current Owner:

Engine top end overhaul by FMS, Fountain Hills, AZ
New valves, guides, rocker arm bearings, etc.
Water pump rebuild
New Clutch
Most rubber hoses in engine bay replaces
Engine bay components powder coated
Brake System Overhaul - calipers, booster, master, most lines replaced
Fuel systems lines replaced, new fuel pump
New AC Compressor/Condenser coil/engine bay hoses
Carbs rebuilt, bottom intake plates resurfaced
Carb phenolic spacer remanufactured
Alternator, Starter, fan motors rebuilt
Exhaust headers Jet Hot Coated
External bright work rechromed
Radiator and heater cores pressure tested
New spark plug wires, distributor rotors and covers