



Service Repair Order

200 SW 12th Ave
Pompano Beach, FL 33069
Ph: 954-958-0000
Fx: 954-946-4756

Date	R/O #
10/22/2015	1010

Customer Name and Address					Cell Phone	Home Phone	
					877-561-2121		
Make	Model	Year	Color	VIN	Mileage	Lic #	
Fer	TR	1988	Red	ZFFAA17B000073399	7,401 KM		
QTY	Description				Price Per	Total	
2	TR Timing Belt #120731				\$ 42.58	\$ 85.16	
2	Bearing Assembly				\$ 123.92	\$ 247.84	
4	Output Seal Rt				\$ 60.25	\$ 241.00	
1	Air Pump Belt				\$ 40.41	\$ 40.41	
1	Alt Belt				\$ 33.32	\$ 33.32	
1	A/C Belt				\$ 31.10	\$ 31.10	
4	O-Ring				\$ 9.97	\$ 39.88	
1	Cam Cover Gasket				\$ 196.09	\$ 196.09	
1	Cam Cover Gasket				\$ 283.55	\$ 283.55	
12	O-Ring				\$ 13.43	\$ 161.16	
1	Cam End Gasket				\$ 29.54	\$ 29.54	
1	Cam End Gasket Alt.				\$ 23.32	\$ 23.32	
1	Seal Ring				\$ 2.72	\$ 2.72	
2	Dist. Support Gas.				\$ 21.09	\$ 42.18	
2	Seal Ring				\$ 28.56	\$ 57.12	
2	Dist. Gap Gas				\$ 8.00	\$ 16.00	
2	Gasket Alt.				\$ 7.62	\$ 15.24	
4	Seal Ring Ferrari				\$ 4.66	\$ 18.64	
2	Fuel Filter - Ferrari				\$ 49.58	\$ 99.16	
1	Air Filter - Ferrari				\$ 71.74	\$ 71.74	
1	Oil Filter - TR				\$ 66.13	\$ 66.13	
2	Hose				\$ 42.75	\$ 85.50	
1	Seal Ring				\$ 8.54	\$ 8.54	
1	Lock Washer				\$ 9.80	\$ 9.80	
1	Ring Back Plate				\$ 14.62	\$ 14.62	
1	Coolant Pump Seal				\$ 30.54	\$ 30.54	
1	Seal Ring				\$ 21.36	\$ 21.36	
1	Belt				\$ 19.71	\$ 19.71	
2	Distr. Cap				\$ 150.00	\$ 300.00	

2	Rotor	\$ 124.59	\$ 249.18
12	Spark Plugs	\$ 11.58	\$ 138.96
4	Exhaust Gasket Alt	\$ 11.55	\$ 46.20
4	Exhaust Gasket Donut	\$ 15.78	\$ 63.12
1	Thermostat	\$ 51.75	\$ 51.75
1	Thermostat Gasket	\$ 14.60	\$ 14.60
1	Coolant Tank Cap	\$ 38.68	\$ 38.68
1	Sealant	\$ 38.10	\$ 38.10
1	Seal Ring	\$ 15.38	\$ 15.38
1	Seal Ring Alt	\$ 50.62	\$ 50.62
1	Coolant Hose	\$ 127.44	\$ 127.44
1	Front Brake Pads	\$ 114.56	\$ 114.56
1	Rear Brake Pads	\$ 168.59	\$ 168.59
1	Caliper Rebuild Kit - Front	\$ 475.77	\$ 475.77
1	Caliper Rebuild Kit - Rear	\$ 153.75	\$ 153.75
8	Caliper Half Seals	\$ 0.99	\$ 7.92
4	Brake Hose	\$ 54.49	\$ 217.96
1	Sublet Brake Caliper Re-Plating	\$ 320.00	\$ 320.00
Total:			\$ 4,583.95



International Auto Group
200 SW 12th Ave
Pompano Beach, FL 33069
www.iagclassics.com
ph: 954-958-0000
fx: 954-946-4756

Ferrari Testarossa Engine Out Service (1985-1991)

The engine out service with timing belt replacement on the Testarossa includes the following:

- 1) Disconnect all lines, hoses, linkages and accessories in the engine compartment for engine removal.
- 2) Remove air intake scoop and exhaust
- 3) Remove engine from vehicle
- 4) Pressure wash engine block and transmission
- 5) Remove camshaft covers, timing belt covers, and other accessories
- 6) Replace timing belt tensioner bearings and tensioners
- 7) Rebuild water pump, replace seals and o-rings
- 8) Replace camshaft seals and camshaft housing o-rings
- 9) Repaint as necessary camshaft covers with correct red wrinkle paint
- 10) Replace timing belt and tension to factory specification
- 11) Set camshaft timing
- 12) Replace a/c and accessory belts
- 13) Replace cooling hoses as needed per visual inspection
- 14) Install camshaft covers and timing belt covers
- 15) Replace spark plugs
- 16) Replace air filter
- 17) Replace fuel filters
- 18) Test spark plug wires and replace as necessary
- 19) Replace clutch and throwout bearing
- 20) Install engine
- 21) Rebuild fuel distributors and clean/flow test injectors
- 22) Evacuate and recharge a/c system as needed
- 23) Test battery and charging system
- 24) Replace engine oil and filter
- 25) Replace gearbox oil
- 26) Replace engine coolant
- 27) Replace and bleed brake fluid
- 28) Inspect brake components, pads, lines and replace as needed
- 29) Detail and clean engine bay while engine is out of car
- 30) Set tire pressure and re-torque wheels
- 31) Road Test

Total labor: 60 hours @ \$125/hour; \$7500.00