



Invoice

Date	Repair Order
4/12/16	3058

Christopher Sebesta
(281) 924-8997

3233 West 11th Street, Unit J2
Houston, TX 77008
mark@spheremotorsports.com
(832) 277 - 7062

VIN #	Year	Car Make	Model	Colour	Miles	Tech
ZFFPR48A3S0103152	1995	Ferrari	355 Spider	Silver	25974	ST
Item	Description			Qty	Rate	Amount
Parts	FS.FER.35527.SHDR Fabspeed headers.			1	2,999.95	2,999.95T
Labour	Install headers.			8.5	127.50	1,083.75
Shipping	All shipping bills			1	55.00	55.00
Labour	De-sticky the remainder of the interior.			1	250.00	250.00
HVAC panel	HVAC panel 355			1	150.00	150.00T
Labour	Re-align roof and make sure it works correctly.			2	127.50	255.00
62175300	Hood strut			4	42.68	170.72T
Labour	Replace front and rear hood struts.			1	127.50	127.50
Roof Oil	Ferrari Roof Oil			1	57.21	57.21T
355 Roof straps	Set of roof straps for middle bar.			1	285.00	285.00T
						5,434.13
Shop Supplies Surcharge	3% of Total Invoice to a Maximum \$175.00				3.00%	163.02
Thank you for your business!				Sales Tax (8.25%)		\$302.19
				Total		\$5,899.34
				Payments		\$0.00
				Balance Due		\$5,899.34