



"Visual Inspection" by Galen's Tag Service, LLC.

For this serial number

RM23H9G285564



Requested by

William F. Kelly



The inspection includes the following categories: V.I.N., body codes, fender tag, body, trim, glass, interior, engine, engine compartment, trunk, chassis and details. Furthermore I inspect the engine and transmission for originality.

ALL NUMBERS MATCHING
REMARKS

V.I.N. (ORIGINAL)	FENDER TAG (ORIGINAL)	I-BODY-2 (CORRECT)	ENGINE (ORIGINAL)	TRANSMISSION (ORIGINAL)	BROADCAST (INCORRECT)	MONROONEY (MISSING)
----------------------	--------------------------	-----------------------	----------------------	----------------------------	--------------------------	------------------------

Galen's Tag Service, LLC

01-05-2016

Inspection Date

Galen V. Govier, Managing Member

No. 1617001

P.O. Box 556
Plymouth, MI 48150-0556
Phone: 313-486-0556
Fax: 313-486-0556

Galen's Registry

No 1617001

January 08, 2016

William F. Kelly,

As of the above date, all of the following information is accurate to my knowledge.

1969 383-4BBL PLYMOUTH Road Runner 2 Door Hardtop VIN RM23H9G285564 is now in the Registry.

There were 31,397 - 1969 383-4BBL PLYMOUTH Road Runner 2 Door Hardtop's built to Spec's for U.S.A. 18,191-4 Speeds and 13,206-Autos. Canadian and Export figures are unknown.

VEHICLES CURRENTLY REGISTERED IN GALEN'S REGISTRY

As of the above date, it is # 422 of 528 in VIN sequence of all 1969 383-4BBL PLYMOUTH Road Runner 2 Door Hardtop's accounted for at the St. Louis, MO plant and built to spec's for the U.S.A.

1969 383-4BBL PLYMOUTH Road Runner 2 Door Hardtop's were also built at the Lynch Road, MI and Los Angeles, CA plants

For identifying major and minor vehicle parts, ask about the Volume I and II Part & Casting Numbers Book for 1962-1974 Chrysler Vehicles.

If there is anything, I can do for you do not hesitate to write.

Galen's Tag Service, LLC

Galen V. Govier
Managing Member

Registered
324-RM23H9A-USA
015-RM23H9A-CANADA
070-RM23H9A-EXPORT
113-RM23H9E-USA
526-RM23H9G-USA

GVG:gg

Note: This vehicle has been inspected and appraised in person by Galen's Tag Service, LLC.
Availability of items and prices are subject to change without notice.

Keep the Faith

Galen's Registry

Page 2

January 08, 2016

As of the above date, all of the following information is accurate to my knowledge. In reference to your inquiry, I have completed the following additional research for **RM23H9G285564**.


These are only numbers of vehicles that are accounted for, these are not complete amounts.

The amounts below include all **U.S.A.** ordered **RM23H9's** accounted for to date. They also include the **CANADIAN** and **EXPORT** ordered cars accounted for.

These are all the RM23H9's "accounted for" according to Galen's Registry.						
Plant "G"				Plant "A"	Plant "E"	
To date: yours is	# 422 of	528 -	RM23H9's registered in VIN sequence.	324	118	
and yours is	# 192 of	253 -	RM23H9's " w/R11-AM Radio.	0	68	
and yours is	# 151 of	196 -	RM23H9's " w/D32-Transmission.	93	42	
and yours is	# 119 of	156 -	RM23H9's " w/Column+D32-Combo.	71	28	
and yours is	# 33 of	38 -	RM23H9's " w/H2G-Trim.	23	9	
and yours is	# 8 of	12 -	RM23H9's " w/V21+V6W-Stripes.	3	0	
and yours is	# 7 of	11 -	RM23H9's " w/A15-Package.	0	0	
and yours is	# 5 of	6 -	RM23H9's " w/F3-Roof & Body Paint.	3	0	
and yours is	# 1 of	1 -	RM23H9's " w/Above Combination.	0	0	
THE CHANCES OF FINDING ANOTHER SIMILAR VIN WITH THE ABOVE COMBINATION OF OPTIONS IS: 10 %!						

If there is anything, I can do for you do not hesitate to write.

Galen's Tag Service, LLC.



Galen V. Govier
Managing Member

GVG/gg

Note: This vehicle has been inspected and appraised in person by Galen's Tag Service, LLC.
Availability of items and prices are subject to change without notice.

Keep the Faith

No. 1617001

P.O. Box 416
Plymouth, Michigan, W. 48150-0416
(504) 325-6346 Office
(504) 326-8661 Fax

Galen's Registry

Page 3

January 08, 2016

As of the above date, all of the following information is accurate to my knowledge. In reference to your inquiry, I have completed the following additional research for **RM23H9G285664**.

The amounts below include all U.S.A. ordered 1969 PLYMOUTH Road Runner 2 Door Hardtop's built. Detailed production numbers are not available for CANADIAN or Export ordered vehicles.

There were	46,869	-	RM23*9 Shipments to the U.S.A.
THE ABOVE NUMBERS ARE ACCURATE; THE NUMBERS BELOW ARE A PERCENTAGE OF THE U.S.A. SHIPMENTS			
And there were	45,649	-	RM23*9's w/E63-Engine, 383 485L.
And there were	41,806	-	RM23*9's w/H11-Heater.
And there were	40,260	-	RM23*9's w/R11-Radio, AM.
And there were	39,791	-	RM23*9's w/S79-Steering Wheel, Panta-Huffing.
And there were	39,229	-	RM23*9's w/B31-Brakes, HD Drum.
And there were	38,752	-	RM23*9's w/STD-Mirror, LH Manual.
And there were	27,699	-	RM23*9's w/O91-Differential Sure-Grip.
And there were	26,945	-	RM23*9's w/STD-2 Speed Wipers.
And there were	24,371	-	RM23*9's w/E65-D32-Combc.
And there were	23,153	-	RM23*9's w/STD-Manual Steering.
And there were	20,997	-	RM23*9's w/V21-Wheels, Road-14".
And there were	20,294	-	RM23*9's w/STD-Glass, All Clear.
And there were	16,451	-	RM23*9's w/V21-Paint, Performance Hood.
And there were	10,545	-	RM23*9's w/M31-Mouldings, Bolt Line.
And there were	8,249	-	RM23*9's w/V60-Stripe, Spot Tape.
And there were	4,359	-	RM23*9's w/T87-Tires, F70-14 RWL.
PRESERVATIONS: MORE PAINT AND TIRE AND/OR ENGINE AND PAINT CAPABLE OF DELIVERY DEL.			

If there is anything, I can do for you do not hesitate to write.

Galen's Tag Service, LLC

Galen V. Govier
Managing Member

GVG:gg

Note: This vehicle has been inspected and appraised in person by Galen's Tag Service, LLC.
Availability of items and prices are subject to change without notice.

Keep the Faith

No. 1617001

Detailed Visual Inspection

Galen's Tag Service, LLC
P.O. Box 516
Prairie du Chien, WI 53591-0516
(608) 328-6348

This is to certify that I am a recognized authority on 1962-1985 DODGE, CHRYSLER & PLYMOUTH Automobiles.
In making this detailed Visual Inspection, I do not agree to purchase or to replace the articles.
I hereby certify that I have this day examined the following listed and described articles, for the person named below:

William F. Kelly

VEHICLE DESCRIPTION								
1969 PLYMOUTH Road Runner 2 Door Hardtop								
V.I.N.	R M 2 3 E 9 G 2 8 5 5 6 4						MILEAGE	37,083
AREA				CONDITION				
01 BODY & PAINT: Top/Bottom: F3-Frost Green Metallic in poor condition. Paint is baked down to bare metal in many places. Caps & seizes in body. J54 Hood: Correct. V21 & V6W Straps: Faced. Radiator support is black. Correct. 5 of Six								
02 CHROME & GLASS: Exterior trim: Correct. Poinsett: Correct. Solar Glass: Incorrect. Backlight: Correct. Acrents: Incorrect. Nameplates: Correct. Side Markers are: Correct. Outside Mirror: Correct. 5 of Six								
03 INTERIOR & SEATS: Interior trim: H2G. Ft Seats: Incorrect. Headliner: Poor. Dash pad & carpet: Poor. Instruments: Correct. Steering Wheel: Poor. Radio: Correct. Shifter: Correct. Seat belts: Removed. 3 of Six								
04 ENGINE: Air Cleaner: Correct. Carburetors: Incorrect. Valve Covers: Correct. PCV: Correct. Intake manifold: Correct. Exhaust manifold: Correct. Fan Assembly: Correct. 3 of Six								
05 ENGINE COMPT: Radiator: Correct. Wiper Mtr: Correct. Horn: Correct. Washer tank: Correct. Battery: Incorrect. Positive battery cable: New. Negative battery cable: Incorrect. Master cylinder assembly: Correct. Steering gear assembly: Correct. Fuel filter: Incorrect. 4 of Six								
06 TRUNK: Deck lid: Correct. Quarter panels: Original. Trunk floor: Original. Trunk mat: Missing. Bumper jack assembly: Missing. Spare tire/assembly: Missing. Spare wheel: Missing. 5 of Six								
07 CHASSIS: Driveshaft: Correct. Transmission: Correct. Axle: Correct. Leaf springs: Correct. Air shield: Correct. Fr Brakes: Correct. U-bolts: Correct. Rr Brakes: Correct. Exhaust: Incorrect. K-Frame: Correct. Sway Bar: Correct. Floor pans: Correct. Wheel wells are: Correct. 3 of Six								
08 TIRES/WHEELS: Size/Make/Brand: BF Goodrich RVR. Radial T/A. Incorrect. 1 H/RH tire runs: Incorrect. Wheel/Wheel covers: Width/Style: 14x5.5" Styled Road Wheels w/Tim Rings. Correct. 3 of Six								
09 SAFETY CK: Everything is good working condition, except Back-up Lights, etc. Rear seat belts: Removed. 3 of Six								
10 OVERALL IMPRESSION: A drivable vehicle needing a complete restoration of body, paint and interior. 1 of 13 306 - Automatic's built for and sold new in the U.S.A. 4 of Six								
MODIFICATIONS/REMARKS: Negatives are dents and evaporated paint and decals. Interior seat covers. No jack, spare or mtr. Positives are near perfect rust-free body, unrestored/original car. Excellent project car. Road Runner Spring Special Package. CONDITION rating includes ACCURACY								
In consideration of present condition = GRADE 4.0								
ALL NUMBERS MATCHING REMARKS	V.I.N. (ORIGINAL)	FENDER TAG (ORIGINAL)	1-BODY-2 (CORRECT)	ENGINE (ORIGINAL)	TRANSMISSION (ORIGINAL)	BROADCAST (INCORRECT)	MONARCHY (MISSING)	
	I	II	III IV	V	VI	+		
Investment GRADE VI - ;=Worst ;=Best ;=less paperwork ;=new and ;=no more cap work								
The foregoing Visual Inspection is made with the understanding that the Inspector assumes no liability with respect to any action that may be taken on the basis of this inspection.								
01-05-2016 INSPECTION DATE				Galen V. Govier, Managing Member No. 1617001				

VEHICLE CONDITION SCALE

1. EXCELLENT: Restored to current maximum professional standards of quality in every area, all correct components operating and appearing as new. A 95-plus point show car that is not driven.
2. FINE: Well-restored, or a combination of superior restoration and excellent original. Also an extremely well maintained original showing minimal wear. NOTE: Looks like # 1 w/incorrect parts
3. VERY GOOD: Completely operable original or "older restoration" showing wear. Also, a good amateur restoration, all presentable and serviceable inside and out. Plus combinations of well-done restoration and good operable components or partially restored car with all parts necessary to complete and/or valuable N.O.S. Parts. IE: Average. NOTE: Looks like # 2 w/incorrect parts
4. FAIR: A driveable vehicle needing no or only minor work to be functional. Also, a deteriorated "restoration" or a very poor amateur restoration. All components may need restoration to be "excellent" but the car is mostly usable "as is"
5. RESTORABLE: Needs complete restoration of body, chassis and interior. May or may not be running but isn't weathered, wrecked or stripped to the point of being useful only for parts
6. PARTS CAR: May or may not be running, but is weathered, wrecked and/or stripped to the point of being useful primarily for parts.

COLOR: DESIRABLE ORIGINAL COLOR: No

ENGINE ☒ STANDARD ENGINE CID/CARB: 383/1498L

TRANS ☒ AUTOMATIC

SHIFT ☒ COLUMN SHIFT

☒ HEATER

MAJOR/DESIRABLE OPTIONS. See second of fender tag

DOCUMENTS ☒ ORIGINAL FENDER TAG
☒ INCORRECT BROADCAST SHEET
☒ OWNERS MANUAL
☒ ORIGINAL or REPRODUCTION WINDOW STICKER

DEALERS NAME/ADDRESS: DANIELS in Colorado Springs, CO. Dealer Code: _____

ORIGINAL OWNERS NAME Mr. & Mrs. Martinez Delivery Date: _____

PROOF OF ABOVE INFORMATION: Nameplate on trunk lid and title history.

NOTES: The following individuals may have had ownership interest in this vehicle. JJ Hostetter in CO (Nephew).

First owner: William F. Kelly

Unrestored

1969 PLYMOUTH Road Runner 2 Door Hardtop

+	5	+
END		
A15	M21	M31 R11 V21 V6W
F3	F3	H2G F8 61Q 392036
E63	D32	M23 H9G 285564

The Fender Tag is read from Left to Right and from Bottom to Top

E63 Engine: 383 1-4bb1 335hp V8 383 ROAD RUNNER ENGINE
 D32 Transmission: A727 Torqueflite Automatic COLUMN SHIFT
 RM Car Line: PLYMOUTH Road Runner
 23 Body Type: 2 Door Hardtop
 H Engine: 383 1-4bb1 335hp V8 383 ROAD RUNNER ENGINE
 9 Model Year: 1969 Z-SERIES
 3 Assembly Plant: St. Louis, MO
 285564 Assembly Plant Sequential Number

 F3 Roof Paint: Frost Green Metallic
 F3 Body Paint: Frost Green Metallic
 H Trim Grade: High
 2 Front Seat: Vinyl Bench
 2 Interior: Green
 F8 Upper Door Frame Color: Dark Green
 61Q Scheduled Production Date: Tuesday June 10, 1969
 392036 Vehicle Order Number

 A15 Road Runner Spring Special Package B-Less Vinyl Roof
 --- Manual Drum Brakes
 --- Outside LH Manual Chrome Mirror STANDARD
 M21 Mouldings: Drip Rail
 M31 Mouldings: Body Belt
 R11 Radio: Music Master AM
 V21 Performance Hood Paint Treatment
 V6W Stripe: White Longitudinal Sport REFLECTIVE TAPE

 END End of fender tag codes.

 5 Inspector's stamp

Decoded for:

William F. Kelly

Decoded by:

Galen's Tag Service, LLC.
 P.O. Box 516
 Prairie du Chien, WI 53821-0516

Note: This vehicle has been inspected and appraised in person by Galen's Tag Service, LLC.
 Availability of items and prices are subject to change without notice.

Thank You

No. 1617001

January 08, 2016