

201211024

Order Date 11/15/12 05:02 pm  
Closed/Paid: 12/05/12 03:34 pm

TRANSFERED TO A/P NO ADD

BAR #: AK105357  
630 Mary Ann Drive  
Redondo Beach, Ca 90278  
Phone: 310-937-6700 FAX: 310-376-3392

	87 Ferrari 328 GTS BLK/TAN	Quotes	
		1 11/15/12 05:03pm	0.00
	Last in 11/2/2016	ERIC in person.	
	Lic: ?/CA V8Cyl 3.2 Eng		

- 1) INSPECT VEHICLE
- 2) OIL AND FILTER CHANGE ?
- 3) OIL PAN
- 4) AC RECHARGE
- 5) SLOW DOWN LIGHT ( 02 SENSOR )
- 6) RUNS BAD WHEN COLD

Job01 PARTS	Labor: \$0.00
-------------	---------------

891.5020.1	MULTI-SOLVENT-N	4.0 @	5.74 =\$	22.96	
460.16.22	WASHER,COPPER 16X20MM-N	1.0 @	0.43 =\$	0.43	
NCBPC-13	CLEANER,PARTS WASH-N	1.0 @	3.23 =\$	3.23	
111334	BELT,TIMING-N	2.0 @	37.10 =\$	74.20	
PT308	PULLY BEARING KIT-S	1.0 @	175.00 =\$	175.00	
ZX001	COOLANT,ZEREX-N	1.0 @	14.77 =\$	14.77	
98HP43	OIL, MOBIL 1 15-50W-N	11.0 @	9.62 =\$	105.82	
FPN00191993	FILTER, OIL,288,246,27-N	1.0 @	33.70 =\$	33.70	
99100120	GASKET SET V/C-N	1.0 @	238.14 =\$	238.14	
99100216	SEAL SET CAM.-N	1.0 @	236.32 =\$	236.32	
121655	BELT, W/P-N	1.0 @	26.40 =\$	26.40	
130493	BELT,ALTERNATOR-N	1.0 @	29.03 =\$	29.03	
105046	BELT A/C-N	1.0 @	48.50 =\$	48.50	
DR8EIX	SPARK PLUG, NGK 6681 I-N	8.0 @	5.70 =\$	45.60	
147676	GASKET,OIL PAN-N	1.0 @	50.65 =\$	50.65	
126699	EXTENSION,PLUG-N	8.0 @	23.53 =\$	188.24	
460.10.14	WASHER,COPPER 10X14-N	2.0 @	0.28 =\$	0.56	
460.8.12	WASHER,COPPER 8X12-N	4.0 @	0.22 =\$	0.88	
61402500	CAT TEMP ECU-U	1.0 @	607.50 =\$	607.50	
FL36	FLASHER RELAY-S	1.0 @	19.21 =\$	19.21	1921.14

Status: Completed Tech: 02

Job02 NOVEMBER 16 - TECH # 36	Labor: N/C
-------------------------------	------------

-----&gt;-----&gt;-----&gt;---Continued on the next page---&gt;-----&gt;-----&gt;-----&gt;

201211024

Order Date 11/15/12 05:02 pm  
Closed/Paid: 12/05/12 03:34 pm

TRANSFERED TO A/P NO ADD

BAR #: AK105357  
630 Mary Ann Drive  
Redondo Beach, Ca 90278  
Phone: 310-937-6700 FAX: 310-376-3392

Job02 NOVEMBER 16 - TECH # 36

NOVEMBER 16 - INSPECTION--FERRARI 328 GTS, VIN# 73101, MILEAGE 36893, TECHNICIAN -TOMMY  
A/C HOSE FROM COMPRESSOR IS BLOWN, OIL LEAKS - CAM SEALS ARE SEEPING, UNDERSIDE OF ENGINE  
IS SOAKED WITH OIL, RECOMMEND CLEANING AND RAN THROUGH HEAT CYCLES TO IDENTIFY SOURCE.  
TURN SIGNALS AND HAZARDS ARE INOPERABLE--LIKELY DUE TO FLASHER RELAY, OIL PAN REPAIRED  
WITH JB WELD, COOLANT LEAK FROM ALUMINUM PIPE IN FRONT OF MOTOR TO LOWER HOSE, TIGHTENED  
CLAMP AND PRESSURIZED SYSTEM TO 15PSI--NO ISSUES AT THIS TIME, LEAK FOUND FROM WATER PUMP  
GASKET WITH SYSTEM PRESSURIZED, LEAK IN VALLEY OF MOTOR, SOURCE UNIDENTIFIED, WEAR ON  
DRIVER'S SEAT, DOOR HINGES HAVE RESISTANCE AND SQUEAK, POOR RUNNING DUE TO INJECTORS, CAT  
TEMP ECU.

BRAKE & TIRES- LEFT FRONT - PADS = 7MM, ROTOR = 21.22MM, TIRE = 6MM  
RIGHT FRONT - PADS = 7MM, ROTOR = 21.1MM, TIRE = 6MM  
LEFT REAR - PADS = 8MM, ROTOR = 21.5MM, TIRE = 6MM  
RIGHT REAR = PADS = 8MM, ROTOR = 21.38MM, TIRE = 6MM  
SPEC ROTOR MINIMUM THICKNESS = 20MM FRONT

Job03 NOVEMBER 21 = TECH # 36

Labor: \$690.00

NOVEMBER 21 - MAJOR SERVICE--PUT CAR ON RACK AND DRAINED FLUIDS, REMOVED AIRBOX, FUEL  
DISTRIBUTOR, CAP ROTOR, WIRES, ACCESSORY BELTS AND MOUNTS, A/C COMPRESSOR, TIMING BELT  
COVER AND REAR VALVE COVER

Job04 NOVEMBER 26 - TECH # 36

Labor: \$460.00

NOVEMBER 26 - REMOVED FRONT VALVE COVER, SET TO TDC #1 AND ATTACHED DEGREE WHEEL, REMOVED  
FUEL INJECTORS, INSPECTED AND FOUND EXCESSIVE CARBON BUILD UP, HOOKED UP EACH INJECTOR TO  
TESTER/CLEANER--ALL INJECTORS OPENING AT 5 BAR = GOOD, INITIAL SPRAY PATTERNS WERE  
SCATTERED AND DRIPPING, ALL INJECTORS ARE SPRAYING CORRECTLY AFTERING CLEANING, ORDERED  
REPLACEMENT O-RINGS FOR INJECTOR HOUSINGS

Job05 NOVEMBER 27 - TECH # 36

Labor: \$690.00

NOVEMBER 27 - PERFORMED CYLINDER LEAKDOWN TEST:  
RESULTS:

1) = 2%  
3) = 4%  
5) = 5%  
7) = 3%  
2) = 4%  
4) = 3%

-----&gt;-----&gt;-----&gt;---Continued on the next page---&gt;-----&gt;-----&gt;-----&gt;

201211024

Order Date 11/15/12 05:02 pm  
Closed/Paid: 12/05/12 03:34 pm

TRANSFERED TO A/P NO ADD

BAR #: AK105357  
630 Mary Ann Drive  
Redondo Beach, Ca 90278  
Phone: 310-937-6700 FAX: 310-376-3392

Job05 NOVEMBER 27 - TECH # 36

6) = 4%

8) = 5%

PERFORMED VALVE ADJUSTMENT AND CHECKED CLEARANCE

ADJUSTED TO SPEC = 0.20 - 0.25MM INTAKE AND 0.35MM- 0.40MM EXHAUST

RESET MOTOR TO TDS #1, REMOVED CAMS AND CAM SEALS, REPLACED SEALS AND  
O-RINGS

Job06 4850 SHIPPING

Sublet: \$90.54

NOV-27 T RUTLANDS W  
NOC-28 RICAMBI AMERICA  
DEC-03 T RUTLANDS W

Job07 NOVEMBER 28 - TECH # 36

Labor: \$172.50

NOVEMBER 28 - REPLACED DISTRIBUTOR SEALS AND CLEANED PARTS

Job08 NOVEMBER 29 - TECH # 36

Labor: \$690.00

NOVEMBER 29 - INSTALL HILL ENGINEERING TIMING BELT TENSIONER PULLEYS, FIT TIMING BELTS,  
DEGREED CAMSHAFTS TO SEPC.

Status: Completed Tech: 02

Job09 NOVEMBER 30 - TECH # 36

Labor: \$575.00

NOVEMBER 30 - TORQUED CAM SPROCKETS, CAPS AND TIMING BELT TENSIONERS TO SPEC.  
FITTED VALVE COVERS AND GASKETS, CHECKED SPARK PLUG EXTENSIONS, MISMATCHED, ORDERED  
EXTENSION SET, LOW RESISTANCE REQUIRED. INSTALLED CAP AND ROTOR, FUEL INJECTORS, A/C  
COMPRESSOR MOUNT AND COMPRESSOR AND ACCESSORY BELTS.

Status: Completed Tech: 02

Job10 DECEMBER 3 - TECH # 36

Labor: \$747.50

-----&gt;-----&gt;-----&gt;---Continued on the next page---&gt;-----&gt;-----&gt;-----&gt;-----&gt;

201211024

Order Date 11/15/12 05:02 pm  
Closed/Paid: 12/05/12 03:34 pm

TRANSFERED TO A/P NO ADD

BAR #: AK105357  
630 Mary Ann Drive  
Redondo Beach, Ca 90278  
Phone: 310-937-6700 FAX: 310-376-3392

Job10 DECEMBER 3 - TECH # 36

---

DECEMBER 3 - INSTALLED FUEL DISTRIBUTOR, COOLANT, PIPES AND VACUUM HOSES, CONNECTED A/C LINES WITH NEW O-RINGS. FILLED COOLING SYSTEM AND PRESSURE TEST @ 17 PSI, NO LEAKS. REMOVE DIPSTICK MOUNT AND OIL PAN, RESEALED PAN WITH NEW GASKET. CHANGED OIL FILTER AND FILLED WITH 11 QTS, OF OIL. REPLACED AIR FILTER, INSTALLED NEW SPARK PLUG CAPS, RAN CAR TO OPERATING TEMP., REPLACED BAD CATALYST TEMPERATURE ECU.

---

Status: Completed Tech: 02

Job11 DECEMBER 4 - TECH #36

Labor: \$345.00

---

DECEMBER 4 - SET OIL LEVEL. CHECKED OVER WORK. SET TIRE PRESSURES TO 32 PSI AND TORQUED WHEELS TO 87 FT LBS. INSTALLED REAR DECK LID AND ADJUSTED. TEST DRIVE WITH CRAIG = PASS. PUT BACK ON RACK AFTER HEAT CYCLES AND CHECK FOR LEAK, NON FOUND. REPAIR TURN SIGNAL FLASHER RELAY AND CHECK ALL LIGHT

---

Job12 DECEMBER 4 - TECH #06

Labor: N/C

DETAIL VEHICLE

---

Status: Completed Tech: 02

Recommendations: AC SYSTEM

---

I agree to pay reasonable attorney fees if legal action becomes necessary to enforce collection of debt. All warranties on products sold hereby are those made by the manufacturer. Fast Cars Ltd. hereby expressly disclaims all warranties, either expressed or implied, including implied warranty of merchantability or fitness for any items on this invoice. Should I Choose to use Visa/Master card or American Express for payment of this invoice, it is understood that I will be responsible for any credit card processing fees.

Work accepted by \_\_\_\_\_ Date \_\_\_\_\_

Fast Cars, Ltd. offers service & restoration for the most unique, complex & expensive automobiles made. The business philosophy of this company is to offer the highest standard of work available without compromise. The guidelines of the State of California, Consumer Protection Act covering automotive repair were drafted to cover main stream automotive repair & do not take into consideration the unique characteristics of the automobiles nor the long term nature of the work performed by this company. Therefor

-----&gt;-----&gt;-----&gt;---Continued on the next page---&gt;-----&gt;-----&gt;-----&gt;

201211024

Order Date 11/15/12 05:02 pm  
Closed/Paid: 12/05/12 03:34 pm

TRANSFERED TO A/P NO ADD

BAR #: AK105357  
630 Mary Ann Drive  
Redondo Beach, Ca 90278  
Phone: 310-937-6700 FAX: 310-376-3392

nor the long term nature of the work performed by this company. Therefor

As the owner or authorized agent of the above referenced automobile, I authorize the repair or restoration work detailed above, along with the necessary parts & materials. I also request the examination of any system that may appear to be deficient.

I acknowledge the unique hand built nature of my automobile & understand that it is impossible for Fast Cars, Ltd. to estimate the exact cost of repairs. Therefore I agree that this estimate is an approximation of charges & is not a binding absolute ceiling to the final cost of repairs or restoration.

I acknowledge that the extraordinary value of my vehicle dictates that I maintain full liability & comprehensive insurance coverage while my vehicle is in possession of Fast Cars, Ltd. I understand that my insurance is the primary coverage & therefore I will not hold Fast Cars, Ltd. responsible for loss or damage to the vehicle or it's contents, in the case of accident, fire, theft, or any other cause beyond reasonable control. I authorize the employees of Fast Cars, Ltd. to operate my vehicle for the purposes of testing, inspection or delivery at my sole risk.

I acknowledge an expressed mechanics lien on this vehicle to secure payment to Fast Cars, Ltd. in the full amount due for repairs. I agree to pay reasonable attorney's fees if legal action becomes necessary to enforce the collection of debt. I agree to pay any difference between the total cost of repairs & payments made by my insurance company. Billing will be sent out on the completion of, biweekly or monthly basis dependant on the duration & work load. Billing is due & payable on receipt, absolutely no term applies. Interest, calculated at 10% per year will be charged on an unpaid balance. Storage at \$50.00 per day will be charged, beginning the day after notification

I take full responsibility for the operation of my high performance or racing car, acknowledging the dangers of operation therein & the potentially lethal consequences.

Owner or agent \_\_\_\_\_ Date \_\_\_\_\_

Payments to Fast Cars Ltd

Cost Summary

Status: Closed Work Order

Payments: \$6,555.78

1 12/05/12 6555.78 AMEX

Labor	4370.00
Parts	1921.14
Sublet	90.54
Haz Waste	6.00
Tax	168.10
Total	\$6555.78
Payments	6555.78
Bal Due	0.00

Thank you for choosing Fast Cars Ltd